



Make 3 cables: FW1, 2, 3

Cold Bulkhead DB15HD Plug to Stepper Motor and Sensor Plug Cable	
D. Clemens, Mimir Project, IAR Boston University	
Rev 1.4	ID 1_004_1.4_Cold_Plug_to_Motor_Unit
Date: 01/02/2003	Page: 1 of 1